## GENDURANCE

# OGIO<sup>®</sup> ENDURANCE Origin Jacket. OE503



COTTON-RICH SOFTNESS STAY-COOL WICKING LAYERABLE WARMTH

- 64/36 cotton/poly flatback knit
- OGIO Endurance heat transfer label for tag-free comfort
- Zip-through collar
- Exposed coil zipper with molded cord pull
- Stacked O heat transfers at center back
- Welded front zippered pockets with locking pulls
- O Endurance heat transfer at right pocket
- Raglan sleeves with welded, articulated elbows
- O heat transfer at upper left sleeve
- OGIO binding at cuffs and hem
- Slight drop tail hem

### CARE INSTRUCTIONS

Machine wash cold with like colors. Remove promptly. Only non chlorine bleach when needed. Tumble dry low. Cool iron if needed. Do not dry clean




front



back

#### **HOW TO MEASURE**



## CHEST

With arms down at sides, measure around the upper body, under arms and over the fullest part of the chest.

## SIZE CHART

	XS	S	М	L	XL	2XL	3XL	4XL
Chest	32-34	35-37	38-40	41-43	44-46	47-49	50-53	54-57

## COLOR INFORMATION



Aluminum Grey Blacktop PMS HEATHERED PMS NTR BLACK C